





Cable seen as comming out from detector



2011-07-01

Connector on FEC seen from top